

Continuum and Control






Possible Schemes and Laboratory Locations





Continuum and Signatures





^{*} might be delegated to a CBTL

Testing outside a CBTL



	Testing on Premises	Witnessed Testing	Supervised Testing	
TÜV Mark	OK	OK	OK	
GS Mark	OK	NO	NO	 Manufacturer
NRTL	OK	OK	OK	
CB Scheme	OK	OK	OK	

TÜV Mark	OK	OK	OK	
GS Mark	OK	NO	NO	Third Party other than
NRTL	OK	OK	OK	CBTL
CB Scheme	NO	NO	NO	

Slide

Testing outside a CBTL



	Testing on Premises	Witnessed Testing	Supervised Testing	
TÜV Mark	OK	OK	OK	
GS Mark	OK	NO	NO	Manufacturer
NRTL	OK	OK	OK	
CB Scheme	OK	OK	OK	

Migration / Outsourcing

TÜV Mark	OK	OK	OK	
GS Mark	OK	NO	NO	Third Party other than
NRTL	OK	OK	OK	CBTL
CB Scheme	NO	NO	NO	

Slide